

## **KILNS, FURNACES, DRYERS & R.T.O "PROVEN IN PRODUCTION"**






## REFRACTORY AND FIBRE




Ceramic fibre and refractory bricks are fundamental to ensuring the efficient operation of your kiln. As refractory bricks degrade over time, the insulation quality of your kiln decreases. This has several negative effects:

- · Your kiln's heat efficiency is reduced, requiring more fuel and costing more to operate.
- · It becomes more difficult to maintain temperature uniformity, requiring more frequent calibration and increasing the risk of product spoilage.
- · Firing cycles become longer and you may need to decrease your product loads.











## THERSER (UK) LTD

Walley Street Buildings, Walley Street, Burslem, Stoke on Trent, Staffs, ST6 2AH T: +44 (0) 1782 824453 | F: +44 (0) 1782 813227 | E: sales@therseruk.com Company Registration No. 06843333 | VAT Registration No. 948547669







